

WINDRUSH COMMUNITY CONDO ASSOCIATION EXTERIOR REMODEL WEEKLY INSPECTIONS

TO: John Soluits 603-344-9977 otisnh@gmail.com

DATE:9/12/2021 - TIME IN:1:00pm TIME OUT: 2:09pm

FROM:
Busby Custom Builders
Ronnie Busby
1998 Cove Dr.
Largo, FL 33774
727-418-2014
ronnie@busbycustombuilders.com
License # C-10282/RR282811685

BUILDING Z Units 1 - 14

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.

BUILDING Y Units 15 - 28

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.

BUILDING T Units 29 - 32

COMMENTS:

New Gable stucco work

Window sills have been replaced with new wood window sills.

BUILDING X Units 33 - 46

COMMENTS:

Window sills have been replaced with new wood window sills.

New stucco on south gable

New stucco on north and south gables above unit 46

All new staircases

Concerned that there is no new footing underneath main 6x6 support post for units 45 and 46





BUILDING W Units 47 - 66

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.

BUILDING V Units 67 - 80

COMMENTS:

Gable stucco work above unit 80

Window sills have been replaced with new wood window sills.

Concerned about under size footing under new 6x6 support post.



BUILDING S Units 81 - 86

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.

BUILDING R Units 87 - 92

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.

BUILDING Q Units 95 - 98

COMMENTS:

New wood framing on upper wall

Window sills have been replaced with new wood window sills.

BUILDING P Units 99 - 104

COMMENTS:

No new work has been started, other than window sills have been replaced with new wood window sills.